

LAZER
HIGH PERFORMANCE LIGHTING
WWW.LAZERLAMPS.COM

LAZER
HIGH PERFORMANCE LIGHTING

CARE INSTRUCTIONS

CARE INSTRUCTIONS

Lazer Lamps products utilise anodised aluminium materials to achieve superior thermal conductivity. Anodised materials react differently to certain chemicals, for this reason it is recommended to use an **Isopropyl Alcohol (IPA)** cleaner on our products.

Lazer Lamps warranty does not cover visual defects that may occur as a result of aggressive chemical cleaning solutions (see our website for additional chemical compatibility lists) or abrasive materials. If in doubt of the suitability of a specific cleaner, we recommend performing a patch test for 24hr first on a hidden area of the extruded lamp body first.

